




A




B





C




D






















Observe


Cleaning


Correct


Incorrect





























1




2




1




2




3







4




5



6




7




8


△ T°C	e
> 20°C	7mm
< 20°C	10mm




9




10



1



2





IMPORTANT, PLEASE READ CAREFULLY AND KEEP FOR FUTURE REFERENCE

1. You may notice a slight variation in colour during the first month of use. This is normal.

2. Profiles must be stored in a dry and ventilated environment, away from direct exposure to sunlight.

Store and transport the profile horizontally

When handling long profiles (>2m) seek the help of a second person

3. Exercise caution when using electrical products and power tools outdoors.

Please strictly follow the manufacturer's safety instructions and never use electrical equipment outdoors when it is raining.